


This surface should be painted black.

Notes:  
1) During assembly Items 4 and 5 should be used to clamp together Items 1, 2 and 3. Items 6 and 7 are used to attach GE-10056 to the field and should be kept with the assembly.

REVISION HISTORY			
ZONE	REV	DESCRIPTION	DATE
	A	see sheet 2	12/11/2009



Resources		
Resource	Description	Quantity
1	3/8" thick clear polycarbonate	AR
2	3/4" Plywood	AR
3	1/2" Plywood	AR

PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	GE-10056-01	Robot Shield
2	1	GE-10056-02	Spacer 3/4"
3	1	GE-10056-03	Spacer 1/2"
4	4	HW-00017	Tee Nut, 1/4-20 Zinc Plate
5	4	HW-00047	1/4-20 x 2.75" Hex Head Bolt, Zinc Plated
6	4	HW-00011	1/4-20 Wing Nut
7	4	HW-00021	Washer, Fender 1/4" Zinc Plate

DRAWN dfoster		12/2/2009		<b>FIRST</b> 200 Bedford Street, Manchester, NH 03101 (603) 666-3906 -- FAX (603) 666-3907	
CHECKED					
UNLESS OTHERWISE SPECIFIED TOLERANCES: (INCHES)				TITLE	
FRAC.		+/- 1/32		Retainer Assembly	
.00		+/- .01		SIZE	
.000		+/- .005		C	
ANGULAR		+/- .25 Deg.		DWG NO	
				GE-10056	
				REV	
				A	
				SCALE	
				SHEET 1 OF 2	

